

Case Study 3

This gentleman is a double amputee and is a bagger. He has a below knee amputation on the left side, and has a syme amputation on the right side. He has been walking on car tires for 20 years.



Assessment reveals knee flexion contractures in flexion on both sides (130/20/0 L and 130/30/0 R) and muscles weakness. What is your treatment plan and fitting decision? Justify your answer

